CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRRES20215679Address:2036 SW WHEATFIELD CT, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Mitchell Schwarz	Failed	Wednesday, June 08, 2022
Corrective Action Required:			
1 Misc	 -top plate penetration between garage doors -Uncover porch framing for inspection -Address joists bored closer than 2" to bottom of joist throughout garage -Sister over notched studs at exterior garage wall all locations (sisters stud to be full length) -Fireblock soffit line at owner's entry/ kitchen -fireblock hvac chase -Protect nm less than 1.25" to face of framing thorough out -Address holes in joists bored closer together than 2" and closer than 2" to bottom throughout kitchen -address rafters landing on blocks throughout -support dwv above 2nd floor hall bath -provide proper slope for dwv above 2nd story hall 		

Comments: