

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20210263

Address: 1801 NW OBRIEN RD, LEES SUMMIT, MO 64081520 NW HOPE LN, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Commercial	Robb Popp	Partial	Tuesday, June 14, 2022

Corrective Action Required:

1 Miscellaneous
 Correction

Corrective Action Required:

2 SECOND FLOOR : THE FOLLOWING AREAS ARE APPROVED :

- 2ND FLOOR AREA A
- UNITS 2021,2022,2023,2024,2025,2027,2029,2004,2005,2006,2008

Corrective Action Required:

3 THIRD FLOOR : THE FOLLOWING AREAS ARE APPROVED :

:: 3ND FLOOR AREA A :
3004, 3005, 3006, 3008, 3021,3022,2023,3024,3025,3027,3029

Corrective Action Required:

4 FOURTH FLOOR THE FOLLOWING AREAS ARE APPROVED:

::AREA A:
4004-4006, 4008,4021-4025,4027,4029

Corrective Action Required:

5 FIFTH FLOOR AREA "A"

Corridor 7 to BUILDING B OK FOR RC CHANNEL

5024- complete sprinkler to balcony, and in laundry, nail exterior corners 12" oc, seal penetrations at service panel, at closet, bonding screws and jumpers at metallic boxes, Bocca at sprinkler in closet

5029-complete sprinklers

5022-finish sprinklers, fire caulk penetration by patio, Bocca plates at sprinkler lines throughout

5021-Bocca plates at sprinklers,strap top plate lapped less than 48" at bedroom, seal gaps at dead space in bathroom, finish sprinkler at deck, protect sprinkler at deck, putty packs at corridor to cover whole box

5027- putty packs to cover whole box at corridor, seal Fireblocking at dead space in bathroom, fire caulk, complete sprinkler at bedroom, strap top plates lapped less than 48" at corridor wall in bedroom and bath, Bocca plates at sprinklers,

5023-finish sprinklers, Bocca plates at sprinklers, seal penetrations at service panel, support SEC above bath

5025-Complete draft stop at corridor, Bocca plates at sprinklers, relocate cat 5 in master bed,

5006-Bocca at sprinkler

5004,5005- Bocca plates at sprinkler at bottom plate

5008-fire collars at roof drains in chase

Comments: