

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20213072
Address: 1225 NE GOSHEN DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

| Inspection: | Inspector: | Outcome: | Date: |
|------------------------|--------------|----------|--------------------------|
| Erosion Control | Khanh Nguyen | Failed | Wednesday, June 15, 2022 |

Corrective Action Required:

| | | |
|---|----------------------------|--------------------------------------------------------------------------------------------------------------------|
| 1 | DCM3 ESC REQUIRED 2 DAY | -EROSION CONTROL REQUIRED. REPAIR EROSION CONTROL NEAR THE STORM INLET -OVERGROWN VEGETATION SHALL BE MOWED |
|---|----------------------------|--------------------------------------------------------------------------------------------------------------------|

****FAILURE TO CORRECT THE ABOVE DEFICIENCIES WILL RESULT IN AN
ISSUANCE OF A STOP-WORK ORDER**

Comments:

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20213072
Address: 1225 NE GOSHEN DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

| Inspection: | Inspector: | Outcome: | Date: |
|------------------------|--------------|----------|--------------------------|
| Erosion Control | Khanh Nguyen | Failed | Wednesday, June 15, 2022 |

Corrective Action Required:

| | | |
|---|----------------------------|--------------------------------------------------------------------------------------------------------------------|
| 1 | DCM3 ESC REQUIRED 2 DAY | -EROSION CONTROL REQUIRED. REPAIR EROSION CONTROL NEAR THE STORM INLET -OVERGROWN VEGETATION SHALL BE MOWED |
|---|----------------------------|--------------------------------------------------------------------------------------------------------------------|

****FAILURE TO CORRECT THE ABOVE DEFICIENCIES WILL RESULT IN AN
ISSUANCE OF A STOP-WORK ORDER**

Comments: