

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20202637
Address: 1001 SE BAILEY RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Above Ceiling Inspection	Robb Popp	Partial	Thursday, June 16, 2022

Corrective Action Required:

1	THE FOLLOWING AREAS ARE APPROVED	2 EAST EXTERIOR CANOPIES-OK NORTH EXTERIOR CANOPY-OK WEST EXTERIOR CANOPY OK -CLEARSTORIES AT A,B,C -SOFFITS AT: CLEAR STORY A100, B100A -HARD LIDS AT A213, B114, 121A, B113, C100A ,,B115,B117,C101A,C10,C10A,C129,C127,C121,C115D,C102-C104, C208, C214, C20 ***BUILDING A: A111,A112,A113, A100A,A100C,,A13,A110B,A101, A103, A104, A105, A106 A108,A108A,A110,A110A,117A,117B,118,118B A202, 203, 204, 205, 207, 208, 209, 210,21,200A,23,24,220A BUILDING B: 101-103, 105-108, 110, 110A, 111,112, 117,118, 121, 121C, 122, 201-206, 208, 209, 211, 212, 214A, 215, 216, 216A, CORRIDORS EXCEPT AT B10 AND AT RATED ASSEMBLIES ***B113,B115, B121C, B121D, B122, B121, B121B,121D,B120, B119 B212, B201, B203, B204-OK
---	----------------------------------	--

***BUILDING C: 101,101A,106-109, 111-113, 119, 120, 122-126, 128-131,
201-204, 211, 212, ,115-115C, 217A-217D, 219-219C, ALL CORRIDORS EXCEPT AT
RATED ASSEMBLIES

**C102, C104, C115A, C115B, C115C ,C117, C118, C119,C210, C206, C207 OC216,
C216B,OK FOR BORDERS ONLY

AREA D

- 1/27/22 HARD LIDS: D103 MEDIA CENTER, D101, D101, A la carte counter,
G108D -
D102, D104, D105, D103, D107, D108, D109, D110,D13, SOFFIT AT VESTIBULE
D100, D11,D12

AREA E:

-E114B, E115, E118, E117B

-E10 CORRIDOR HARD LID SOFFITS

Area E: E123, E124, E122, E101, E102, D103, E104, E105, E106, E107, E109, E109,
E10, E111, E112, E114A, E117A, E11A,E11B, E10
HARD LID OUTSIDE E123&124

AREA F: 104A,104B

AREA G: 102,103,106,107,108,108B,108F, G109, G108B, G108F, G108, G101,
G10A-B, G11,

Corrective Action Required:

2 Misc

Corrective Action Required:

3 Misc

3/11/22 - D110A OK

HARD LID OUTSIDE OF E123/E124 OK

F104 RECALL WHEN GRID INSTALLED

B10/C10 CORRIDOR SET (2) SPRINKLER HEADS AT SOUTH END OF B10, LOOSE
MC ABOVE DISPLAY CASES, DRIVERS FOR LOW VOLT LIGHTING ON
BACKORDER, FIRECAULK PENETRATIONS AND ADDRESS GAP AT ROCK TO DECK
AT NORTH END OF C10 2 HOUR RATED ASSEMBLY, OTHER AREAS OK

I

Comments: