

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20214555, Public Works Right of Way Permit
Address: 1050 NW INNOVATION PKWY, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

| Inspection: | Inspector: | Outcome: | Date: |
|------------------------------|------------|----------|------------------------|
| Site Visit Inspection | Nick Scott | Passed | Tuesday, June 21, 2022 |

Corrective Action Required

| | | |
|---|------|---|
| 1 | Misc | Crews are onsite in the vicinity of the railroad tracks. The crew was informed to contact the Water Department to locate the Sanitary Sewer main near the tracks. |
|---|------|---|

Corrective Action Required

| | | |
|---|------|---|
| 2 | Misc | No restoration efforts have been made. Bare ground with clay and rock. No erosion control. This site borders a creek. I left a voicemail with Dennis (Earthworkz) and spoke with Brandon Fossett with UPN. Brandon stated that he would get the area restored ASAP. |
|---|------|---|

Corrective Action Required

| | | |
|---|------|---|
| 3 | Misc | Site visited and it appears that grass seed and straw have been put down. Will return in a couple weeks to check on the grass growing |
|---|------|---|

Corrective Action Required

| | | |
|---|------|---|
| 4 | Misc | Site visited and grass has not started growing will come back march 1st and check again |
|---|------|---|

Corrective Action Required

| | | |
|---|------|---|
| 5 | Misc | Site visited and only 10% of the vegetation has grown back. I will be in contact with Earthworkz to have them come out and do more restoration. |
|---|------|---|

Corrective Action Required

| | | |
|---|------|--|
| 6 | Misc | Site visited and restoration has grown back passed |
|---|------|--|

Comments: