CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20216072

Address: 524 SE DAVID RD, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Patrick Schonfeldt Failed Friday, June 24, 2022

Residential

Corrective Action Required:

1 Misc -nail garage PFH sheathing per plans

- -nail all exterior sheathing per plans
- -deck ledger attachment per code
- -provide (2) 1/2" through bolts at each post/beam connection per code -address top plate corner lap connection, dbl car to sgl car garage wall,
- different plate heights
- -address top plate corner lap connection at garage walls to front entry wall,
- see East garage wall
- -tighten all anchor bolts at garage
- -fireblock unused top plate bore at garage entry closet
- -address top plate corner lap connection at great room exterior wall to kitchen and master bed walls
- -fireblock fireplace at master bed wall open to attic above ceiling line
- -seal all top plate penetrations at great room
- -have engineer with truss manufacturer address broken trusses above foyer
- -dbl girder truss landing on block at foyer, no H2.5 hold down clips
- -address top plate corner lap connection at front bed to front entry wall
- -provide blocking at sheathing edge and nail per plans, see front bed
- -CS-PF portal design per plans at dining room widows and sliding glass door see plans/IRC R602.10.6.4 for reference
- -min 24" lap between dbl top plate breaks, see master bed

- -WSP panel interior and exterior side of wall at great room per plans
- -fireblock vertical every 10' between studs and foundation/framing at finished basement fireplace between top plate and foundation/top plate throughout finished basement
- -seal all top plate penetrations at finished basement
- -fireblock vertical to horizontal at furred down soffit ends finished basement
- -tighten panel bonding screw at service panel
- -osb at interior and exterior of wall at basement den windows per plans
- -provide 3" SCH 40 steel column at pier location "B" per plans at beam unfinished/storage
- -complete plumbing above basement bedroom closet

Comments: