



# LEE'S SUMMIT, MISSOURI FIRE DEPARTMENT LOSS REDUCTION PROGRAM



## NOTIFICATIONS/CONTACT INFORMATION SECTION

PAGE 1

### ☐ CHANGES

BUSINESS NAME	National Bank of Kansas City		
ADDRESS	350 SW BLUE PKWY, LEES SUMMIT, MO 64063		
OWNER/OPERATOR NAME	LYTLE CONSTRUCTION INC:	TELEPHONE	(816) 524-7275
ADDRESS	1100 SE HAMBLER RD LEES SUMMIT, MO 64081 Primary: (816) 524-7275 Cell: <NO CELL PHONE> STAN @ 806-4661		

## EMERGENCY CONTACT INFORMATION

NAME	TELEPHONE
1.	
2. ON FILE	
3.	
4.	

## LOSS REDUCTION TYPE

<input checked="" type="checkbox"/> Occupancy	<input type="checkbox"/> Semi-Annual	<input type="checkbox"/> Annual	<input type="checkbox"/> Life Safety	<input type="checkbox"/> Sprinkler	<input type="checkbox"/> Hazardous Material Permit
<input type="checkbox"/> Complaint	<input type="checkbox"/> Explosive Storage	<input type="checkbox"/> UST	<input type="checkbox"/> Post-Incident	<input type="checkbox"/> Open Burning	<input type="checkbox"/> Other
CLASS: B	Map#: 195K	PFA#:	KNOX BOX:	KNOX LOCATION:	PERMIT # PRCOM20100205

## LOSS REDUCTION NARRATIVE

### ☐ NO CORRECTIONS NOTED

### ☐ ALL CORRECTIONS COMPLETED

Last Inspection

1st Inspection 2/17/11

2nd Inspection

3rd Inspection

4th Inspection

INSPECTION	INSPECTOR	OUTCOME	DATE
Occupancy Inspection - Fire	Joe Dir	Temporary C of O	Thursday, February 17, 2011
Corrective Action Required: 1 PRCOM20100205 (1) Post the suites address on the rear door (2) NW glass man door - remove the address and label the door with the wording " THIS DOOR BLOCKED" Corrective Action Required: 2			
DATE OF REPORT	INSPECTOR	PREVENTION FOLLOW-UP REQUIRED?	RESPONSIBLE SIGNATURE
February 17, 2011	Joe Dir	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	

