

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20204940
Address: 322 NW AMBERSHAM DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Robb Popp	Failed	Friday, June 24, 2022

Corrective Action Required:

1	Misc	-Fire stop at landing both sides of wall, fire stop from stud wall to joist space at landing. (not done) -THIS SHOULD SEAL OFF VERTICAL TO HORIZONTAL AT JOISTS -Seal all beam pockets-SEAL ALL FINISHED SPACES -FIREBLOCK CEILING LINE IN BASEMENT BED-MISSING BLOCK -FIREBLOCK DEAD SPACE IN BASEMENT BED -3" Bath fan vents not allowed
---	------	---

Comments: