



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20222793, Public Works Right of Way Permit

Address: 1405 SW GEORGETOWN DR, LEES SUMMIT, MO 640821533 SW GEORGETOWN DR, LEES SUMMIT, MO 640824408 SW LODESTONE DR, LEES SUMMIT, MO 640821705 SW HIGHTOWN DR, LEES SUMMIT, MO 640821809 SW HIGHTOWN DR, LEES SUMMIT, MO 640821901 SW HIGHTOWN DR, LEES SUMMIT, MO 640824402 SW AMETHYST DR, LEES SUMMIT, MO 640824401 SW ALABASTER CIR, LEES SUMMIT, MO 640824420 SW ALABASTER CIR, LEES SUMMIT, MO 640824400 SW ALABASTER CIR, LEES SUMMIT, MO 640824421 SW TANZANITE CIR, LEES SUMMIT, MO 640824400 SW TANZANITE CIR, LEES SUMMIT, MO 640824421 SW GRINDSTONE CIR, LEES SUMMIT, MO 640824400 SW GRINDSTONE CIR, LEES SUMMIT, MO 640821913 SW MERRYMAN DR, LEES SUMMIT, MO 640821937 SW MERRYMAN DR, LEES SUMMIT, MO 640821932 SW HIGHTOWN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Matt Munger	Partial	Wednesday, June 29, 2022

Corrective Action Required

1 Misc

Site Visit - The crew was onsite, they were using a directional bore to install the conduit. They had crossed SW Merryman along SW Georgetown. I spoke with one of the workers onsite and he stated they were 3ft in depth at the crossing. I did observe them also using compactors as they were filling in the holes. Monitoring.

Comments: