



HD Engineering & Design

Solutions for all your engineering and design needs

June 29, 2022

Wood Brothers Construction

RE: 3126 SW Blue Ribbon Street, Lee's Summit, MO (PRRES20203584)

Our firm has been asked to address a rough framing inspection item for the home being built at the location listed above. At the time of inspection the home was in a rough framed state.

The inspector has questioned the hip rafter above the master bathroom/closet. The framer has installed a coil strap per the inspector's suggestion.

Our firm has reviewed the existing framing conditions and found that the rafter to top plate connection in this area is adequate to transfer the loads as intended.

Our firm recommends approval of this item as framed.

This report has been prepared for the exclusive use of our client for specific application to the project discussed and has been prepared in accordance with generally accepted engineering practices. No warranties, either expressed or implied, are intended or made.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please contact us.



THIS DOCUMENT CONTAINS
COPYRIGHTED MATERIAL AND
CONFIDENTIAL INFORMATION
BELONGING TO HD ENGINEERING.
UNAUTHORIZED USE, DISCLOSURE,
DISSEMINATION, OR DUPLICATION OF
ANY OF THE INFORMATION
CONTAINED HEREIN MAY RESULT IN
LIABILITY UNDER APPLICABLE LAW.

STRUCTURAL REVIEW
HD ENGINEERING & DESIGN
HD: 40101 DATE: 6/29/2022