



HD Engineering & Design

Solutions for all your engineering and design needs

FRAMING INSPECTION RESPONSE

6/28/2022
SAB HOMES
RE: ELLENBROOK (HF63)
2102 SW RED BARN LANE
LEE'S SUMMIT, MO.

Our firm has been asked to address a rough framing inspection item for the home being built at the location listed above. At the time of inspection the home was in a rough framed state. Please find below our firms response and recommendations for the item.

Holes in Portal Framing for Wires

The electrician has drilled horizontal holes for passage of low voltage wires in the lower portion of the portal narrow wall framing. Our firm has reviewed the framing in place and found no conditions that are code violations. The holes will not prevent the portal frame from performing as intended.

Our firm recommends approval this item as framed.

This report has been prepared for the exclusive use of our client for specific application to the project discussed and has been prepared in accordance with generally accepted engineering practices. No warranties, either express or implied, are intended or made.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please contact us.

Very truly yours,
HD ENGINEERING & DESIGN, INC.

John Hulse, Principal



STRUCTURAL REVIEW
HD ENGINEERING & DESIGN
HD: 42615 DATE: 6/28/2022