



# LEE'S SUMMIT MISSOURI



## FIRE DEPARTMENT

### NOTIFICATIONS/CONTACT INFORMATION SECTION

PAGE 1

☐ CHANGES

BUSINESS NAME	NEW LONGVIEW - BUILDING 31 SHELL		
ADDRESS	420 SW LONGVIEW BLVD, LEES SUMMIT, MO 64081		
OWNER/OPERATOR NAME	Monarch Build, LLC:	TELEPHONE	(913) 942-2400
ADDRESS	8100 Newton Street Ste 300 Overland Park, KS 66204 Primary: (913) 942-2400 Cell: <NO CELL PHONE>		

### EMERGENCY CONTACT INFORMATION

NAME	TELEPHONE
1. _____	
2. _____	
3. _____	
4. _____	

### LOSS REDUCTION TYPE

<input type="checkbox"/> Occupancy	<input type="checkbox"/> Semi-Annual	<input type="checkbox"/> Annual	<input type="checkbox"/> Life Safety	<input type="checkbox"/> Sprinkler	<input type="checkbox"/> Hazardous Material Permit
<input type="checkbox"/> Complaint	<input type="checkbox"/> Explosive Storage	<input type="checkbox"/> UST	<input type="checkbox"/> Post-Incident	<input type="checkbox"/> Open Burning	<input type="checkbox"/> Other
CLASS: N/A	Map#:	PFA#:	KNOX BOX:	KNOX LOCATION:	PERMIT #

### LOSS REDUCTION NARRATIVE

☐ NO VIOLATIONS NOTED

☐ ALL VIOLATIONS RESOLVED

Last Inspection

1st Inspection

2nd Inspection

3rd Inspection

4th Inspection

INSPECTION	INSPECTOR	OUTCOME	DATE
Occupancy Inspection - Fire	Craig Hill	Failed	Friday, June 24, 2022
Corrective Action Required:			
1	Address the building and all spaces, both front and back doors. Exterior emergency egress lighting was not operational and failed. Add emergency egress lighting at the top of each stairwell leading from the two upstairs occupancies.		

1 All life safety was appropriate. Okay to occupy with approval form codes.

DATE OF REPORT	INSPECTOR	PREVENTION FOLLOW-UP REQUIRED?	RESPONSIBLE SIGNATURE
July 01, 2022	Craig Hill	<input type="checkbox"/> Yes <input type="checkbox"/> No	