

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20210263

Address: 1801 NW OBRIEN RD, LEES SUMMIT, MO 64081520 NW HOPE LN, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Commercial	Robb Popp	Partial	Tuesday, July 05, 2022

Corrective Action Required:

1	Miscellaneous Correction	-Provide fire collars at 2008,3008,4008,5008
---	--------------------------	--

Corrective Action Required:

2	SECOND FLOOR	: THE FOLLOWING AREAS ARE APPROVED :
---	--------------	--------------------------------------

- 2ND FLOOR AREA A

- UNITS 2021,2022,2023,2024,2025,2027,2029,2004,2005,2006

**2008-Provide fire collars at dwv in chase

Corrective Action Required:

3	THIRD FLOOR	: THE FOLLOWING AREAS ARE APPROVED :
---	-------------	--------------------------------------

:: 3ND FLOOR AREA A :

3004,3005,3006,3021,3022,2023,3024,3025,3027, 3029

**3008-Provide fire collars at dwv in chase

Corrective Action Required:

4	FOURTH FLOOR	THE FOLLOWING AREAS ARE APPROVED
---	--------------	----------------------------------

::AREA A:

4004-4006,4021-4025,4027,4029

**Provide fire collars at dwv in chase

AREA "B"

-ADDRESS WELDED JOIST HANGERS AT LOBBY 4011-FIREBLOCK DEAD SPACES

4035-OK

4030-OK

4033 OK

4028-OK

4031-address main lugs at panel, joist hangers at deck tension tie joist

4026-OK

Corrective Action Required:

5

FIFTH FLOOR

AREA "A"

THE FOLLOWING AREAS ARE APPROVED:

Corridor 7 to BUILDING B OK FOR RC CHANNEL

5004-5006,5021-5025,5027,5029

***5008-Provide fire collars at roof drains in chase

Comments: