

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20222793, Public Works Right of Way Permit

Address: 1405 SW GEORGETOWN DR, LEES SUMMIT, MO 640821533 SW GEORGETOWN DR, LEES SUMMIT, MO 640824408 SW LODESTONE DR, LEES SUMMIT, MO 640821705 SW HIGHTOWN DR, LEES SUMMIT, MO 640821809 SW HIGHTOWN DR, LEES SUMMIT, MO 640821901 SW HIGHTOWN DR, LEES SUMMIT, MO 640824402 SW AMETHYST DR, LEES SUMMIT, MO 640824401 SW ALABASTER CIR, LEES SUMMIT, MO 640824420 SW ALABASTER CIR, LEES SUMMIT, MO 640824400 SW ALABASTER CIR, LEES SUMMIT, MO 640824421 SW TANZANITE CIR, LEES SUMMIT, MO 640824400 SW TANZANITE CIR, LEES SUMMIT, MO 640824421 SW GRINDSTONE CIR, LEES SUMMIT, MO 640824400 SW GRINDSTONE CIR, LEES SUMMIT, MO 640821913 SW MERRYMAN DR, LEES SUMMIT, MO 640821937 SW MERRYMAN DR, LEES SUMMIT, MO 640821932 SW HIGHTOWN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Matt Munger	Partial	Wednesday, July 06, 2022

Corrective Action Required

1	Misc	Site Visit - Workers were onsite boring along SW Georgetown. I spoke with Junior the foreman onsite, he said everything has been going smooth. A few restoration questions from homeowners. The utility locate did mis marked by 10ft the street light yesterday. Every is aware. There is a section of sidewalk at the corner of SW Lodestone and SW Georgetown on a new home build site that was damaged but not by the contractor. The builder of that home will need to replace once they put the full sidewalk in.
---	------	---

Comments: