CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRCOM20210263Address:1801 NW OBRIEN RD, LEES SUMMIT, MO 64081520 NW HOPE LN, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
All Rough Inspection - Commercial		Robb Popp	Partial	Tuesday, July 12, 2022
Corrective Action Required: 1 Miscellaneous Correction Corrective Action Required:		-Provide fire collars at 2008,3008,4008,5008		
2	SECOND FLOOR	: THE FOLLOWING AREAS ARE APPROVED :		
Correctiv 3	e Action Required: THIRD FLOOR	- 2ND FLOOR AREA A - UNITS 2021,2022,2023,20 **2008-Provide fire collar : THE FOLLOWING AREAS A)5,2006
Correctiv 4	e Action Required: FOURTH FLOOR	:: 3ND FLOOR AREA A : 3004,3005,3006,3021,3022 **3008-Provide fire collar THE FOLLOWING AREAS A		
		::AREA A: 4004-4006,4021-4025,4027 **Provide fire collars at d		

	4011-FIREBLOCK DEAD SPACES AREA "B" 4035-OK 4030-OK 4033 OK 4028-OK 4028-OK 4031-address main lugs at panel, joist hangers at deck tension tie joist 4026-OK
Corrective Action Required:	
5 FIFTH FLOOR	AREA "A"
	THE FOLLOWING AREAS ARE APPROVED:
	5004-5006,5021-5025,5027,5029
	***5008-Provide fire collars at roof drains in chase
	AREA "B"
	-5035-address trusses at entry bored for mc
	-5030-Address trusses at entry bored for mc
	5033-OK
	5028-OK
	5031-OK
	5026-OK

Comments: