CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20214187

Address: 3014 NW THOREAU PL, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Shawn Hoffman Failed Wednesday, July 13,

Residential 2022

Corrective Action Required:

1 Miscellaneous

Correction -Anchor bolts middle third of plate garage

- -Fire block penetration nm garage double bay in header
- -Nail 2x4 to header 2 rows at 3" on center portal frame
- -Nail exterior corner master bedroom near deck
- -Strap top plate entry garage side not tied in
- -Complete nailing LIB pantry
- -Anchor steel columns at refrigerator
- -Nail exterior corners in dining room
- Nail off CSPF at dining room header
- Open covering on deck and front porch or —- provide ladder for inspection
- Fire block soffit ends basement bar/ media
- Through bolts on deck post to beam connections 2&1/2" per post
- Cut tall vegetation on lot

Comments: