CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20210103

Address: 2100 NE INDEPENDENCE AVE, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date: **Detention Basin** Partial Thursday, July 14, 2022 Corrective Action Required: Miscellaneous 3-5-22 AN talk with terry about the basin and how they still need to get it to Correction drain. They have tried multiple times to fix it but it has not worked. Informational: Miscellaneous 3-28-22 AN spoke with Terry again and let him know that we needed the as builts for the structures in the basin and also the basin is still not draining Correction good enough

Corrective Action Required:

Misc 4-7-22 AN. Spoke with terry and they are making an effort to get the water

out of the basin but the rain has made it hard to try and keep it dry.

Corrective Action Required:

4 Misc 4-27-22 AN no work has been done to fix the detention basin except for

pumping water out.

Corrective Action Required:

5 Miscellaneous 5-2-22 AN pics attached. Need to unclog overflow pipe and get silt fence up

Correction or rock checks installed. Excessive amount of silt built up.

7-7-22 RH. Nothing has been done to stop sediment from entering the basin. Still no approved plans for correcting the basin. Their TCO is about to expire I

believe around July 15th.

Informational:

6 Misc 7-14-22 AN fine cut is out and cutting the storm box down and they are using

the approved epoxy for the rebar. When the regrading is being done the

basin also needs to be regraded and the riser pipe also needs to be cleaned
out. We will also need as graded and as builts

Comments: