

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20215409
Address: 940 NW PRYOR RD, Unit:A, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Above Ceiling Inspection	Robb Popp	Failed	Friday, July 15, 2022

Corrective Action Required:

1	Miscellaneous Correction	<ul style="list-style-type: none">-Hood-Provide detail for hood, wrap and banding-Provide plans-Product installed in space prior to approval.-Missing heat ducts over kitchen area.-Repair all damaged fireproofing at structural steel-missing above hood,-Provide certification that fireproofing is installed to proper thickness-Open j boxes at hood-Remove tape from sprinkler head at back hall-Cut drains above floor sinks.-Provide access to gas valve behind soda machine south wall.-Provide Identification (stencil) at fire walls per code-Missing knock out in j box at dining hard lid-Provide screening at CO2 tank at exterior
---	-----------------------------	--

Comments: