


June 30, 2022

Summit Homes 120 SE 30th St. Lee's Summit, MO 64082

RE: Field Issue of over-notched floor joist for Lot #111 Manor at Stoney Creek – 4409 SW Grindstone Circle, Lee's Summit, MO 64082 – Permit # PRRES20216314

Over-notched floor joist:



SIMPLE SPAN

- D1 − 6"
- D2 4"
- Length 1 − 2'
- Length 2 9.5'
- Span 11.75'
- Support #1 W8x15 Steel beam
- Support #2 Foundation wall.
- Location Near basement stairs/ under bath#1.
- Loading
 - o Dead = 15 psf @ 16" oc
 - o Live = 40 psf @ 16" oc

Recommendations:

- Add additional (1) full length #2-2x10 adjacent to over-notched floor joist. Floor joist shall be installed no further than 4" from notched floor joist.
- Install solid blocking at the end supports and fasten to sheathing per 2018 IRC.

Sincerely,

Bradley Huxol, PE

