

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20216314
Address: 4409 SW GRINDSTONE CIR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

| Inspection: | Inspector: | Outcome: | Date: |
|---|--------------------|----------|------------------------|
| All Rough Inspection - Residential | Patrick Schonfeldt | Failed | Tuesday, July 19, 2022 |

Corrective Action Required:

| | | |
|---|------|---|
| 1 | Misc | -Install full depth header at cut joist basement north wall ,header has been ripped. Install correct nails, remove waterlines from header.(NOT DONE, 8 1/2" HEADER DEPTH) -covered deck siding does not extend to top plates , install per code. |
|---|------|---|

Comments: