

CITY OF LEE'S SUMMIT CODES ADMINISTRATION 220 SE GREEN ST. P.O.BOX 1600

PHONE: 816-969-1200

FAX:

816-969-1201

Inspection Summary

Permit #: PRCOM20110161, Building Permit - Commercial Address: 1170 NE DOUGLAS ST, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

In-wall Inspection John Borns Failed Thursday, March 10, 2011

Corrective Action Required

1 MISC PVC AND COPPER PLUMBING PIPE LESS THAN 1-1/2" FROM

FACE OF FRAMING NOT PROTECTED BY SHIELD PLATES AT

OPEN PORTIONS OF WALL

Corrective Action Required

2 MISC COPPER PIPING NOT PROTECTED FROM STEEL STUD EDGE AT

ONE OR MORE LOCATION.

Corrective Action Required

3 MISC MC ELECTRICAL CABLE NOT SECURED WITHIN 12" OF ENTRY

TO SOME BOXES

Corrective Action Required

4 MISC STUD AT MEN'S RR S.E. NOT REINFORCED TO COMPENSATE

FOR REMOVED SECTION OF FLANGE

Corrective Action Required

5 MISC CLEANOUT AT MAIN PLUMBING STACK MUST BE USABLE;

REINFORCE STUD IF PORTION OF FLANGE MUST BE REMOVED.

INSTALL ACCESS PANEL BEFORE FINAL INSPECTION.

Corrective Action Required

6 MISC CLARIFICATION REQUIRED ON WALL TYPE "4A" DESIGNATED AS

"FIREWALL"

Comments: