CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20210103

Informational:

Misc

Address: 2100 NE INDEPENDENCE AVE, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Detention Basin			Partial	Wednesday, July 20, 2022
Corrective Action Required:				
1	Miscellaneous Correction	3-5-22 AN talk with terry about the basin and how they still need to get it to drain. They have tried multiple times to fix it but it has not worked.		
Informational:				
2	Miscellaneous Correction	3-28-22 AN spoke with Terry again and let him know that we needed the as builts for the structures in the basin and also the basin is still not draining good enough		
Corrective Action Required:				
3	Misc	4-7-22 AN. Spoke with terry and they are making an effort to get the water out of the basin but the rain has made it hard to try and keep it dry.		
Corrective Action Required:				
4	Misc	4-27-22 AN no work has been done to fix the detention basin except for pumping water out.		
Corrective Action Required:				
5	Miscellaneous Correction	•	leed to unclog overflow pig Excessive amount of silt bui	•
		_	en done to stop sediment f	~

7-14-22 AN fine cut is out and cutting the storm box down and they are using

believe around July 15th.

the approved epoxy for the rebar. When the regrading is being done the basin also needs to be regraded and the riser pipe also needs to be cleaned out. We will also need as graded and as builts

7-15-22 RH. Should be a crew out next week doing rest of the grading.

7-18-22 AN no work on the basin today

7-19-22 AN no work on the basin today

Comments: