CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRCOM20210263Address:1801 NW OBRIEN RD, LEES SUMMIT, MO 64081520 NW HOPE LN, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: All Rough Inspection - Commercial		Inspector: Robb Popp	Outcome: Partial	Date: Wednesday, July 20, 2022	
					Corrective Action Required: 1 Miscellaneous Correction
	tive Action Required:				
2	SECOND FLOOR	: THE FOLLOWING AREAS ARE APPROVED :			
		- 2ND FLOOR AREA A - UNITS 2021,2022,2023,2024,2025,2027,2029,2004,2005,2006 **2008-Provide fire collars at dwy in chase			
Correc	tive Action Required:				
3	THIRD FLOOR	: THE FOLLOWING A	REAS ARE APPROVED :		
		:: 3ND FLOOR AREA	A :		
		3004,3005,3006,3021	,3022,2023,3024,3025,302	7, 3029	
		**3008-Provide fire	collars at dwv in chase		
		:::AREA B-			
		3035- complete bath mechanical in back	n exhaust, midpoint strap bed	dwv in bath, complete	
			exhaust and mechanical i	n back bed	
		3033-ok			
		3028-ok			

		3031-Address truss bored above island 3026-ok 3011-address ledger connections at elevator,		
Corrective Action Required:		Sorr address reager connections at crevator,		
4	FOURTH FLOOR	THE FOLLOWING AREAS ARE APPROVED		
		::AREA A:		
		4004-4006,4021-4025,4027,4029		
		**Provide fire collars at dwv in chase		
		AREA "B"		
		4011-FIREBLOCK DEAD SPACES		
		4035-OK		
		4030-OK		
		4033 OK		
		4028-OK		
		4031-address main lugs at panel, joist hangers at deck tension tie joist 4026-OK		
Corrective Action Required:				
5	FIFTH FLOOR	AREA "A"		
		THE FOLLOWING AREAS ARE APPROVED:		
		5004-5006,5021-5025,5027,5029		
		***5008-Provide fire collars at roof drains in chase		
		AREA "B"		
		-5035-ОК		
		-5030-OK		
		5033-OK		
		5028-OK		
		5031-OK		
		5026-OK		

Comments: