CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRCOM20210263Address:1801 NW OBRIEN RD, LEES SUMMIT, MO 64081520 NW HOPE LN, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: All Rough Inspection - Commercial		Inspector:	Outcome:	Date:	
		Robb Popp	Partial	Wednesday, July 27, 2022	
Corrective Action Required: 1 Miscellaneous Correction		-Provide fire collars at 2008,3008,4008,5008			
Corrective Action Required 2 SECOND FLOOR		: THE FOLLOWING AREAS ARE APPROVED :			
		- 2ND FLOOR AREA A - UNITS 2021,2022,2023,2024,2025,2027,2029,2004,2005,2006 -2002 ACTIVITIES - OK			
.		2001- seal gaps dead spaces, fireblock ceiling line at existing tie in doorway			
Correctiv 3	e Action Required: THIRD FLOOR	: THE FOLLOWING AREAS ARE APPROVED :			
		:: 3ND FLOOR AREA 3004,3005,3006,3021	A : .,3022,2023,3024,3025,302	27, 302	
		3001- Seal gaps in fireblocking			
		:::AREA B- 3035- complete batł	n exhaust, midpoint strap	dwv in bath, complete	

Corrective Action Required: 4 FOURTH FLOOR	mechanical in back bed 3030-complete bath exhaust and mechanical in back bed 3033-ok 3028-ok 3031-Address truss bored above island 3026-ok 3011-address ledger connections at elevator, THE FOLLOWING AREAS ARE APPROVED ::AREA A: 4004-4006,4021-4025,4027,402, 4001 - Seal gaps in Fireblocking
Corrective Action Required: 5 FIFTH FLOOR	AREA "B" 4011-OK 4035-OK 4035-OK 4030-OK 4033 OK 4028-OK 4028-OK 4028-OK 4028-OK 4026-OK AREA "A" THE FOLLOWING AREAS ARE APPROVED: 5004-5006,5021-5025,5027,5029 5001-seal gaps in fireblocking throughout AREA "B" -5035-OK -5030-OK 5033-OK 5028-OK 5031-OK 5026-OK
- ·	

Comments: