## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #:PRCOM20213681Address:2150 NW LOWENSTEIN DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:	
All Rough Inspection - Commercial	Robb Popp	Partial	Thursday, July 28, 2022	
Corrective Action Required: 1 FIRST FLOOR	THE FOLLOWING AREAS A	ARE APPROVED:		
Corrective Action Deguized	AREA "A" UNITS AND CORRIDORS EXCEPT AS NOTED: 133-incomplete			
Corrective Action Required: 2 SECOND FLOOR	THE FOLLOWING AREAS ARE APPROVED:			
	AREA "A" UNITS AND CORRIDORS AREA "B" UNITS AND CORRIDORS			
	AREA "C" 210-Strap over bored load bearing walls, repair draft stop at separation wall 251-Fireblock ceiling line at dead space corner, fire caulk cop, 250-straps at over bored top plates, fireblocking at ceiling line, add stud at south wall bathroom 253-structural strap at over bored top plate in kitchen and laundry, add stud at bathroom wall 252-strap top plate, protect n, Bocca at hot water in bedroom			
	255-bonding screw and jumper in bath, add stud in bath, fire caulk dwv in dead space			
	254-strap over bored plate at laundry, add studs at bath			

		257-seal dead space at bath, stud at bath		
		256-strap top plate at closet,		
		259-strap over bored top plate at kitchen and laundry, quash block at bedroom,		
		258-strap top plate at kitchen, protect sprinkler pipe at laundry		
		215-ok		
		216-overbored top plate		
		216-ok		
		261-missing nails at joist hanger in bedroom by window, straps at over bored top plates at bathroom		
		218- strap plates lapped less than 48"		
		260- protect nm at kitchen/bed, strap top plates in bedrooms lapped less		
		than 48", fire caulk dead space, strap and stud at laundry wall over bored top		
		plate		
		219,220,221,222,223,224-ok		
		263-Add stud at laundry and bath		
		South corridor at stair d-fireblock ceiling line		
Corrective Action Required:				
3	THIRD FLOOR	THE FOLLOWING AREAS ARE APPROVED:		
		AREA "A" UNITS AND CORRIDORS		
А		AREA "B" UNITS AND CORRIDORS		
		AREA "C" UNITS AND CORRIDORS		
Corrective Action Required:				
4	STAIR TOWER 1	STAIR TOWER "A"		
		-3RD FLOOR OK		
Correctiv	e Action Required:	equired:		
5	STAIR TOWER 2	STAIR TOWER "B"		
		-3RD FLOOR OK		
Corrective Action Required:				
6	STAIR TOWER 3	STAIR TOWER "C"		
		-3RD FLOOR OK		

Comments: