CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20213746

Address: 725 SW 15TH CIR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Mitchell Schwarz Failed Wednesday, August 03,

Residential 2022

Corrective Action Required:

1 Misc

- -Provide 5/8" bolt and plate washer at each side of second PFH-EADT SIDE OF WEST DOOR
- -Tighten anchor bolts-NOT COMPLETE-SEE PFH
- -Fireblock top and bottom of double walls and fireblock vertical 10' oc max-NOT DONE
- -Strap exterior top plates lapped less than 24" at dining room south wall
- -Fireblock dead spaces by fireplace with approved means SEAL GAPS
- -Add full length Jack stud under beam for porch at exterior corner of wardrobe, master bed.
- -Lower Bocca plate to protect 2" below plate at master bath all locations

Comments: