



CITY OF LEE'S SUMMIT
CODES ADMINISTRATION
220 SE GREEN ST.
P.O.BOX 1600

PHONE:
816-969-1200

FAX:
816-969-1201

Inspection Summary

Permit #: PRCOM20110161, Building Permit - Commercial
Address: 1170 NE DOUGLAS ST, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Codes Commercial	John Borns	Failed	Friday, March 25, 2011

Corrective Action Required
1 MISC

ADDRESS LABELING OF ELECTRICAL SERVICE PANELS --
DESIGNATE WHICH METER SERVES EACH PANEL

Corrective Action Required
2 MISC

LABELING OF ELECTRICAL CIRCUITS AT SERVICE PANELS: NEC 408.4; IRC E3606.2. EACH BREAKER MUST BE LABELED. MUST BE LEGIBLE; SPECIFIC. IF PANEL SCHEDULE IS USED NUMBER POSITIONS ON PANEL FRONT PER SCHEDULE. NO DITTO MARKS OR CONTINUATION SYMBOLS EXCEPT @ MULTIPLE POLE BREAKERS. LABEL UNUSED BREAKERS "SPARE"

Corrective Action Required
3 MISC

ADDRESS IDENTIFICATION OF GAS SERVICE ENTRIES: APPLY PERMANENT TAGS TO LOAD SIDE ENTRY PIPE (NOT ON METER).

Corrective Action Required
4 MISC

SOME ELECTRICAL RECEPTACLES AT REAR WALL NOT SECURED SOLID TO BOX -- TIGHTEN

Corrective Action Required
5 MISC

WALL BASE NOT INSTALLED AT SOUTH RESTROOM

Corrective Action Required
6 MISC

NORTH RESTROOM LACKS HANDICAPPED-ACCESSIBLE SIGN

Corrective Action Required
7 MISC

WATER CLOSETS NOT SEALED TO FLOOR SURFACE

Corrective Action Required
8 MISC

AFFIX "NO SMOKING" SIGN AT EACH ENTRANCE TO BE UTILIZED BY PUBLIC

Comments: