



LEE'S SUMMIT, MISSOURI FIRE DEPARTMENT LOSS REDUCTION PROGRAM

NOTIFICATIONS/CONTACT INFORMATION SECTION

PAGE 1

☐ CHANGES								
BUSINESS NAME	Plato's Closet							
ADDRESS	1170 NE DOUGLAS ST, LEES SUMMIT, MO 64086							
OWNER/OPERATOR NAME	BUDDEMEY	ER CONSTRU	JCTION:		TELEPHONE	<no primary<br="">PHONE></no>		
ADDRESS	Primary: <nc< th=""><th>NG DR IIT, MO 6408 PRIMARY P 9-3526 Ron</th><th>HONE></th><th>-215-0775</th><th></th><th>THORE</th></nc<>	NG DR IIT, MO 6408 PRIMARY P 9-3526 Ron	HONE>	-215-0775		THORE		
EMERGENCY CONTACT INFORMATION								
NAME 1.	TELEPHONE							
2. IN FDM								
3.								
4.								
LOSS REDUCTION TYPE								
⊠ Occupancy □ Sen	ni-Annual	☐ Annual	☐ Life Sa	fety	Sprinkler	Hazardous Material Permit		
<u> </u>	losive Storage	UST	Post-In		—	Other		
CLASS: M	Map#: 195B	PFA#:	KNOX BOX	(:	KNOX LOCATION:	PERMIT # PRCOM20110161		
LOSS REDUCTION NARRATIVE								
□ NO CORRECTIONS NOTED ⊠ALL CORRECTIONS COMPLETED								
Last Inspection 1st Inspection 3/25/11 2nd Inspection 3/28/11 3rd Inspection 4th Inspection								
INSPECTION		ECTOR		OUTCOME	DATE			
Occupancy Inspection - Fire Joe Dir Passed Monday, March 28, 2011								
All previous violations corrected, OK to occupy once cleared through codes administration.								
Alarm Test				Passed	Friday, Ma	rch 25, 2011		
					-			
Sprinkler - Hydrostatic Test				Not Require	ed Friday, Ma	rch 25, 2011		
Sprinkler - Flow Test				Not Require	ed Friday, Ma	rch 25, 2011		

Occupancy Inspection - Fire	Joe Dir	Temporary C of O Friday	, March 25, 2011					
Corrective Action Required:								
1 post the designated address on the front and fear doors of 1170, 4" min. in a contrasting color Corrective Action Required:								
2 mount 2A-10BC fire extinguisher close to an exit with the top of theextinguisher no higher than 60" off floor.								
Corrective Action Required:								
replace the painted sprinkler head located above the middle front entry door.								
Corrective Action Required: 4 cover the open j-box located above the storeage room door at the rear of the store.								
bovor the open j box located above the dicreage room abor at the real of the dicre.								
DATE OF REPORT	INSPECTOR	PREVENTION FOLLOW-UP REQUIRED?	RESPONSIBLE SIGNATURE					
March 28, 2011	Joe Dir	☐ Yes ⊠No						