


August 12, 2022

Summit Homes 120 SE 30th St. Lee's Summit, MO 64082

RE: Field Issue of over notched joist for Lot #70 Reserve at Stoney Creek – 1521 SW Georgetown Dr Lee's Summit, MO 64082 – Permit # PRRES20215236





SIMPLE SPAN

- D1-2"
- D2 3"
- Length 1 5' 5"
- Length 2 6'
- Span 11' 8"
- Support #1 Rear LBW at garage
- Support #2 Garage W12 X 26 STL beam
- Location Garage, under bath #2
- Loading -
 - Dead = 15 psf @ 16" oc
 - Live = 40 psf @ 16" oc

Recommended modifications:

• Sister a 6' length DFL #2 2x10 centered on joist notch. Attach with glue and 4 fasteners per linear ft. in a "w" pattern.

2. Over notched floor joist in great room:

- D1 4.5"
- D2 3.5"
- Length 1 9'-6"
- Length 2 5' -2.5"
- Span 15'-11" with a 2' cantilever
- Support #1 Rear LBW at great room
- Support #2 (2) 3.5" X 9.25" LVL
- Location Great room under bath #3.
- Loading -
 - Dead = 15 psf @ 16" oc double every other
 - Live = 40 psf @ 16" oc double every other
 - Point load on cantieliver from floor above

Model No.	Strap Qty.	Installation	Fasteners (Per Strap) (in.)	Allowable Loads DF/SP		Allowable Loads SPF/HF	
				Compression (160)	Tension (160)	Compression (160)	Tension (160)
CTS218	1	One sided	(24) 0.148 x 1 ½	1,125	2,270	970	1,970
	2	One sided		2,250	4,535	1,935	3,900
	2	Two sided		2,515	4,535	2,165	3,900
	3	Two sided		3,310	6,805	2,845	5,850
	4	Two sided		5,035	9,070	4,330	7,800
	1	One sided	(24) #9 x 1½" SD	1,175	2,510	1,010	2,160
	2	One sided		2,350	5,020	2,020	4,315
	2	Two sided		2,735	5,020	2,350	4,315
	3	Two sided		4,130	7,530	3,550	6,475
	4	Two sided		5,470	10,040	4,700	8,635

WWW.EVERSTEAD.COM 3741 NE TROON DR. SUITE 200 LEE'S SUMMIT, MO 64064 816-399-4901

Recommended modifications:

• Install CTS218 strap at top of floor joist on both sides of floor joist per manufacturer's specifications.

Sincerely,

14

Bradley Huxol, PE

