

FIRE DEPARTMENT

NOTIFICATIONS/CONTACT INFORMATION SECTION

PAGE 1

□ CHANGES

BUSINESS NAME	CHASE BANK		
ADDRESS	890 NE LANGSFORD RD, LEES SUMMIT, MO 64063		
OWNER/OPERATOR NAME	TURNER CONSTRUCTION COMPANY:	TELEPHONE	(816) 283-0555
ADDRESS	1220 WASHINGTON STE 1000 KANSAS CITY, MO 64105 Primary: (816) 283-0555 Cell: (816) 398-5703		

EMERGENCY CONTACT INFORMATION

NAME	TELEPHONE
1.	
2.	
3.	
4.	

LOSS REDUCTION TYPE

□ Occupancy □ Ser	ni-Annual	Annual	Life Safety	Sprinkler	 Hazardous Material Permit
🔲 Complaint 🔲 Exp	olosive Storage	UST	Post-Incident	Open Burning	Other
CLASS:	Map#:	PFA#:	KNOX BOX:	KNOX LOCATION:	PERMIT #
В					

LOSS REDUCTION NARRATIVE

	OTED	□ ALL VIOLATIONS RESOLVED			
Last Inspection	1st Inspection	2nd Inspection	3rd Inspection	4th Inspection	
INSPECTION	INSPECTOR	OUT	ICOME D	DATE	
Occupancy Inspection	- Fire Ben Hicks	Fail	ed N	/londay, September 19, 2022	
egress travel.	access doors shall b Access to exits shall	be marked by readily	visible exit signs in	y visible from any direction of cases where the exit or the	

egress travel. Access to exits shall be marked by readily visible exit signs in cases where the exit or the path of egress travel is not immediately visible to the occupants. Exit sign placement shall be such that no point in a corridor is more than 100 feet (30 480 mm) or the listed viewing distance for the sign, whichever is less, from the nearest visible exit sign.Exceptions:1. Exit signs are not required in rooms or areas that require only one exit or exit access.2. Main exterior exit doors or gates that are obviously and clearly

	identifiable as exits need not have exit signs where approved by the fire code official.3. Exit signs are not required in occupancies in Group U and individual sleeping units or dwelling units in Group R-1, R-2 or R-3.4. Exit signs are not required in sleeping areas in occupancies in Group I-3.5. In occupancies in Groups A-4 and A-5, exit signs are not required on the seating side of vomitories or openings into seating areas where exit signs are provided in the concourse that are readily apparent from the vomitories. Egress lighting is provided to identify each vomitory or opening within the seating area in an emergency.
	An approved pictorial sign of a standardized design shall be posted adjacent to each elevator call station on all floors instructing occupants to use the exit stairways and not to use the elevators in case of fire. The sign shall read: IN FIRE EMERGENCY, DO NOT USE ELEVATOR. USE EXIT STAIRS. The emergency sign shall not be required for elevators that are part of an accessible means of egress complying with Section 1007.4.
Corrective	Action required- Fix exit sign in front vestibule Action Required:
2	New and existing buildings shall have approved address numbers, building numbers or approved building identification placed in a position that is plainly legible and visible from the street or road fronting the property. These numbers shall contrast with their background. In multi-tenant commercial buildings where

property. These numbers shall contrast with their background. In multi-tenant commercial buildings where tenants have multiple entrances located on different sides of the building, each door shall be addressed. Address numbers shall be Arabic numerals or alphabet letters. Numbers shall be a minimum of 4 inches (102 mm) high with a minimum stroke width of 0.5 inch (12.7 mm).

Action Required- Add address to front of building over door, additional address Langsford St side of building.

Occupancy permit and approval will be through Developmental Services

DATE OF REPORT	INSPECTOR	PREVENTIO	N FOLLOW-UP	RESPONSIBLE SIGNATURE
September 19, 2022	Ben Hicks	□ Yes		