

## FIRE DEPARTMENT

## NOTIFICATIONS/CONTACT INFORMATION SECTION

PAGE 1			NOTH IOAHONG	OCONTACT INFORMA	THOM DECTION			
_								
☐ CHANGES								
BUSINESS NAME	CHASE BANK							
ADDRESS	890 NE LANGSFORD RD, LEES SUMMIT, MO 64063							
OWNER/OPERATOR NAME	TURNER CONSTRUCTION COMPANY: TELEPHONE (816) 283-055							
	1220 WASHINGTON STE 1000							
ADDRESS	KANSAS CITY, MO 64105 Primary: (816) 283-0555							
	Cell: (816) 39							
		EMERGENC	Y CONTACT INFO	RMATION				
IAME TELEPHONE								
1								
2.								
3.								
4.								
		LOS	S REDUCTION TY	PE				
☐ Occupancy ☐ Se	mi-Annual	☐ Annual	☐ Life Safety	Sprinkler	Hazardous Material			
☐ Complaint ☐ Ex	plosive Storage	UST	□ Post-Incident	Open Burning	☐ Other			
CLASS:	Мар#:	PFA#:	KNOX BOX:	KNOX LOCATION:	PERMIT #			
	l	LOSS R	EDUCTION NARR	ATIVE				
☐ NO VIOLATIONS	NOTED		Пан	VIOLATIONS RESOLV	/FD			
Last Inspection 1st Inspection		2nd	2nd Inspection 3rd Inspection		4th Inspection			
INSPECTION	INSPI	ECTOR	OUTCO	ME DATE				
Occupancy Inspection - Fire Ben Hicks		Failed	Monday,	ay, September 19, 2022				
egress trave path of egre point in a co	it access doors sel. Access to exite set to exite set travel is not in the rridor is more the	s shall be ma nmediately vi an 100 feet (3	rked by readily visi sible to the occupa 30 480 mm) or the	exit sign readily visible ble exit signs in cases v nts. Exit sign placement isted viewing distance in igns are not required in	where the exit or the  It shall be such that no  for the sign, whichever			

require only one exit or exit access.2. Main exterior exit doors or gates that are obviously and clearly

	identifiable as exits need not have exit signs where approved by the fire code official.3. Exit signs are not required in occupancies in Group U and individual sleeping units or dwelling units in Group R-1, R-2 or R-3.4. Exit signs are not required in sleeping areas in occupancies in Group I-3.5. In occupancies in Groups A-4 and A-5, exit signs are not required on the seating side of vomitories or openings into seating areas where exit signs are provided in the concourse that are readily apparent from the vomitories. Egress lighting is provided to identify each vomitory or opening within the seating area in an emergency.								
	An approved pictorial sign of a standardized design shall be posted adjacent to each elevator call station on all floors instructing occupants to use the exit stairways and not to use the elevators in case of fire. The sign shall read: IN FIRE EMERGENCY, DO NOT USE ELEVATOR. USE EXIT STAIRS. The emergency sign shall not be required for elevators that are part of an accessible means of egress complying with Section 1007.4.								
Corrective 2	Action required- Fix exit sign in front vestibule/ Corrected 09/21/22  Action Required:  New and existing buildings shall have approved address numbers, building numbers or approved building identification placed in a position that is plainly legible and visible from the street or road fronting the property. These numbers shall contrast with their background. In multi-tenant commercial buildings where tenants have multiple entrances located on different sides of the building, each door shall be addressed. Address numbers shall be Arabic numerals or alphabet letters. Numbers shall be a minimum of 4 inches (102 mm) high with a minimum stroke width of 0.5 inch (12.7 mm).  Action Required- Add address to front of building over door, additional address Langsford St side of building./ Corrected 09/21/22								
	cy Inspection - Fire	Ben Hicks	Passed	Wedn 2022	esday, September 21,				
Corrective 1	Action Required: Final approval for pe	ermits issued through Do	evelopmental Servi	ices.					
DATE OF REPORT		INSPECTOR	PREVENTION REQUIRED?	I FOLLOW-UP	RESPONSIBLE SIGNATURE				
Septembe	r 21, 2022	Ben Hicks	☐ Yes	□No					