CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRRES20221673Address:2609 SW HOOK FARM LN, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

| Inspection: | | Inspector: | Outcome: | Date: |
|---------------------------------------|-----------------------|---|----------|-------------------------------|
| All Rough Inspection - Residential | | Khanh Nguyen | Failed | Friday, September 23, 2022 |
| Correc | tive Action Required: | | | |
| 1 | Misc | -Fb laundry exterior wall plate penetrations -Secure SE cable within 12" of connection to meter enclosure -Protect kitchen range cable at laundry rm bottom wall plate; at kitchen bottom wall plate; -Install hangers for ceiling beam connections above master bedroom -Protect water lines at bottom wall plates with BOCA plates at: refrigerator, inside master closet -At foyer walls, secure wirings along studs min 1.25" from stud surface -Protect 3" DVW at bedroom 4 -In basement Rec room, provide wall receptacle spacing per code (no more than 12 ft between receptacles) -Provide vertical fire blockings for basement exterior wall at max ten ft interval -Fb gap at top of double stud wall between basement Rec room and bathroom -Support 2" DVW every 4 ft in mechanical room -Interior brace wall will be braced per GB method. Call for inspection after all-rough inspection is approved | | |
| | | **OK TO INSULATE | | |

Comments: