

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20222742, Public Works Right of Way Permit

Address: 11600 NW CHIPMAN RD, LEES SUMMIT, MO 6408111908 NW CHIPMAN RD, LEES SUMMIT, MO 6408111608 NW CHIPMAN RD, LEES SUMMIT, MO 6408111906 NW CHIPMAN RD, LEES SUMMIT, MO 6408111900 NW CHIPMAN RD, LEES SUMMIT, MO 64081701 NW CEDAR CREEK LN, LEES SUMMIT, MO 640812790 NW CHIPMAN RD, LEES SUMMIT, MO 640812718 NW CHIPMAN RD, LEES SUMMIT, MO 6408111905 NW CHIPMAN RD, LEES SUMMIT, MO 64081625 NW EDGEWOOD CT, LEES SUMMIT, MO 64081612 NW CLIFFSIDE CT, LEES SUMMIT, MO 64081613 NW TIMBER RIDGE TRL, LEES SUMMIT, MO 64081612 NW TIMBER RIDGE TRL, LEES SUMMIT, MO 640812775 NW CHIPMAN RD, LEES SUMMIT, MO 640812801 NW CHIPMAN RD, LEES SUMMIT, MO 640812807 NW CHIPMAN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Site Visit Inspection Nick Scott Partial Monday, September 26, 2022

Corrective Action Required

1 Misc Site visited and it appears work has not started.

Corrective Action Required

2 Misc Site visited and it appears locate marks are down. And AT&T. Is

out working.

Corrective Action Required

3 Misc Site visited and it appears workers are out and no one is

working on the road will come back next week to check again.

Corrective Action Required

4 Misc site visited and it appears that Ervin has passed Ceder Creek

and does not have very much longer to bore. All traffic Control

was set up properly.

Corrective Action Required

5 Misc Site visited and Ervin Cable is not working at this location

today.

Corrective Action Required

6 Misc Site visit and it appears all the areas Ervin Cable has restored

the areas with grass seed and straw. Will come back in a couple

weeks to check again.

Comments: