## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

## **Inspection Summary**

Permit #: PRRES20222621 Address: 2071 NW OBRIEN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: All Rough Inspection - Residential		Inspector:	Outcome:	Date:	
		Michael Harkins	Not Ready	Friday, September 30, 2022	
Corrective	e Action Required:				
2	Miscellaneous	Install doors & windows			
	Correction	Seal fire blocking north wall family room ( furr out side gap)			
		SCH 40 columns family room placement not per plan			
		Seal fire blocking at window well & closet bed 3 ( gap at furr out side ) Seal fire blocking BED 5 office ( furr out side gap & line set ) Seal dead space & fire block bed 5 shower ( rock wool / insulation at pex ) Seal fire blocking bed 4			
	Deck ledger flashed but won't be visible on occupancy no under it			cupancy not spaced off from trim	

Comments: