


October 6, 2022

Summit Homes 120 SE 30th St. Lee's Summit, MO 64082

RE: Field Issue of notched floor joist for Lot #34 Woodside Ridge – 2126 NW Ashurst Dr. Lee's Summit, Mo 64081 – Permit # PRRES20222409

Address over notched floor joist for DWV below bath 2:



SIMPLE SPAN

- D1 2.5"
- D2 6"
- Length 1 2'
- Length 2 13.5'
- Span 15.5'
- Support #1 W8x10 continuous steel beam
- Support #2 W8x10 continuous steel beam
- Location under bath #2

Recommended modifications:

- Sister a 6' length DFL#2 2x10 to notched floor joist centered as best possible with notch.
- Glue sistered floor joist and install 4 fasteners per linear ft in a "W" pattern.

Adress overnotched floor joist for 3" DWV in basment near column A:

- D1 3"
- D2 3"
- Length 1 1'
- Length 2 9'
- Span 10'
- Support #1 W8x13 steel beam
- Support #2 W8x10 continuous steel beam
- Location under bath #1

Recommended modifications:

- Sister a 6' length DFL#2 2x10 to notched floor joist centered as best possible with notch.
- Glue sistered floor joist and install 4 fasteners per linear ft in a "W" pattern.

Sincerely,

Bradley Huxol, PE