CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20222149

Address: 2808 SW HEARTHSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Mitchell Schwarz Failed Monday, October 10,

Residential 2022

Corrective Action Required:

1 Misc

- -address rafters landing on blocks throughout
- -anchor bolts to be in the middle third of sill plate in garage
- -seal gap at furred out wall in garage to ceiling space
- -hanger at front entry above front door for double
- -seal return air stud space in bed 2
- -seal penetration in top plate

bath/mast hall entry

- -fireblock stairwell wall to ceiling space
- -address over notched ceiling joist and rafter above dining room
- -fireblock vertical to horizontal every 10' in basement
- -fire block furr out walls to ceiling space in basement
- -seal penetration in RA stud spaces in basement
- -remove return air blocking in basement bed
- -nail off siding to plans and code
- -hanger missing nails at deck
- -ledger missing screws

Comments: