## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #:PRCOM20210263Address:1801 NW OBRIEN RD, LEES SUMMIT, MO 64081520 NW HOPE LN, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Above Ceiling Inspection		Robb Popp	Partial	Friday, October 21, 2022
Corrective	Action Required:			
1	Misc	HARD LIDS		
Corrective 2	e Action Required: SECOND FLOOR	AREA "A"		
		Room 2004 pass		
			trations missing fire box m	issing above fire door
		Room 2006 pass Room 2008 ok		
		Room 2008 ok Room 2010 ok		
		Room 2005 access panels		
		2002-access panels for dar	npers	
		2017 soffits ok		
Corrective Action Required:				
3	THIRD FLOOR	AREA "A"		
		3004 pass		
		3005 pass		
		3006 pass		
		3008 ok		
		3010 ok 3017 sofffits ok		
		JOLT JOINING OK		

Corrective Action Required:

001100011	e / letton nequireur	
4	FOURTH FLOOR	AREA "A"
		4004-ok
		4005-access panels
		4008-ok
		4010-ok
		4006-OK
		Corridor 417 soffits ok
Correctiv	e Action Required:	
5	FIFTH FLOOR	AREA "A"
		5004 seal upward penetrations, provide cover open box
		5006-ok
		5008 ok
		5010-ok
		Corridor 5007 soffit at fire door ok to cover
		5013 ok
		5007-ok
		5001-ok
		5005-access panels
		5004-dampers
		5006-OK
		ALL SOFFIT FRAMING IN CORRIDORS BUILDING B OK
Corrective Action Required:		
6	Miscellaneous	10/21/22- secure mc, missing cover plates, secure lights at opposite corners
	Correction	in corridors

Comments: