CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20210263

Address: 1801 NW OBRIEN RD, LEES SUMMIT, MO 64081520 NW HOPE LN, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Miscellaneous Inspection Michael Harkins Failed Thursday, October 27,

2022

Corrective Action Required:

1 Miscellaneous

Correction

Parking lot located at 1801 NW Obrien Rd - Parking lot a is allowed to be utilized for its intended purpose. Outstanding items noted on the Occupancy inspections completed on 9/21/2021 shall be completed prior to full release.

Corrective Action Required:

2 Misc 10/24/22 PRE FINAL WALK OF UNITS ONLY ON 2A:

- -PROVIDE PERMANENT SIGNAGE THROUGHOUT
- -PROVIDE SPARK RINGS AT ANY AND ALL RECEPTACLES SET BACK MORE THAN 1/4" TO NON COMBUSTIBLE FINISHES, AND EXTENDED TO FACE OF FINISH AT ALL COMBUSTIBLE FINISHES THROUGHOUT
- -ADDRESS THRESHOLD HEIGHTS GREATER THAN 1/2" AT EXTERIOR DOORS THROUGHOUT
- -ACTIVATE AND UNCOVER ALL SMOKE/ COMBO DETECTORS FOR INSPECTION
- -PROVIDE LOCKOUTS AT ALL HARDWIRED APPLIANCES THROUGHOUT

2021- complete throughout items

2022-Provide shower, restroom grab bars, and electrical panel height

compliant with 2017 A117.1. NOT READY

2023-Secure dishwasher discharge line above bowl of sink, COVER PLATE GFCI $\,$

DISHWASHER

2023/2025 mechanical-label disconnects, secure mc, missing sprinkler

escutcheon, cover plates
2024, 2025-ok except for throughout conditions
2027-Seal penetrations at mechanical and secure whip, SPARK RINGS
BEDROOM
2020, Brouide hammer arrester at kitchen, secure dishwacher discharge

2029- Provide hammer arrestor at kitchen, secure dishwasher discharge, provide gfci protection at laundry,seal penetrations in mechanical NOT READY 10/27/22

10/27/22 NOT READY ONLY WALKED UNIT 3027 ADDRESS THROUGHOUT ITEMS AND RECALL WHEN READY

3027 bad GFCI master, spark rings

Comments: