

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20210263

Address: 1801 NW OBRIEN RD, LEES SUMMIT, MO 64081 520 NW HOPE LN, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Above Ceiling Inspection	Robb Popp	Partial	Friday, November 11, 2022

Corrective Action Required:

1	Misc	HARD LIDS *REMOVE PUTTY PACKS AND FIRECAULK ALL PENETRATIONS IN RATED ASSEMBLIES *SECURE ALL MC AND LOW VOLTAGE OFF OF GRID *PROVIDE COVERS AT J BOXES AND KNOCKOUT COVERS AT UNUSED KNOCKOUTS
---	------	---

Corrective Action Required:

2	SECOND FLOOR	AREA "A" Room 2004 pass Corridor 2007 soffits penetrations missing fire box missing above fire door Room 2006 pass Room 2008 ok Room 2010 ok Room 2005 access panels 2002-access panels for dampers 2017 soffits ok 2015,2019 ok
---	--------------	---

Corrective Action Required:

3	THIRD FLOOR	AREA "A"
---	-------------	----------

3004 pass
3005 pass
3006 pass
3008 ok
3010 ok
3017 soffits ok

Corrective Action Required:

4 FOURTH FLOOR

AREA "A"
4004-ok
4005-access panels
4008-ok
4010-ok
4006-OK
Corridor 417 soffits ok
Corridor 4007 to fire wall ok

Corrective Action Required:

5 FIFTH FLOOR

AREA "A"
5004 seal upward penetrations, provide cover open box
5006-ok
5008 ok
5010-ok
Corridor 5007 soffit at fire door ok to cover
5013 ok
5007-ok
5001-ok
5005-access panels
5004-dampers
5006-OK
corridor 5007 to firewall ok

ALL SOFFIT FRAMING IN CORRIDORS BUILDING B OK

Comments: