CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRCOM20210263Address:1801 NW OBRIEN RD, LEES SUMMIT, MO 64081520 NW HOPE LN, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Miscellaneous Inspection		Robb Popp	Partial	Monday, November 21, 2022
Corrective	e Action Required:			
1	Miscellaneous	Parking lot located at 1801 NW Obrien Rd - Parking lot a is allowed to be utilized for its intended purpose. Outstanding items noted on the Occupancy inspections completed on 9/21/2021 shall be completed prior to full release.		
	Correction			
Corrective	e Action Required:		•	
2	Misc	10/24/22 PRE FINAL WALK OF UNITS ONLY AT BUILDING A:		
-PROVIDE PERMANENT SIGN			IGNAGE THROUGHOUT	
		-PROVIDE SPARK RINGS AT ANY AND ALL RECEPTACLES SET BACK MORE THAN		
		1/4" TO NON COMBUSTIBLE FINISHES, AND EXTENDED TO FACE OF FINISH AT		
		ALL COMBUSTIBLE FINISHES THROUGHOUT		
		-UPDATE PANEL SCHEDULES TO REFLECT ACCURATE LABELING THROUGHOUT		
		-ACTIVATE AND UNCOVER ALL SMOKE/ COMBO DETECTORS FOR INSPECTION		
		2021- complete throughout items		
		2022-Provide shower, restroom grab bars, and electrical panel height		
		compliant with 2017 A117.1. NOT READY		
		2023-Secure dishwasher discharge line above bowl of sink, COVER PLATE GFCI DISHWASHER		
		2023/2025 mechanical- la escutcheon, cover plates	bel disconnects, secure mc,	, missing sprinkler
		2024, 2025-ok except for		

2027-Seal penetrations at mechanical and secure whip, SPARK RINGS BEDROOM

2029- Provide hammer arrestor at kitchen, secure dishwasher discharge, provide gfci protection at laundry, seal penetrations in mechanical NOT READY 10/27/22

3029-install shower head and hvac, secure discharge line above bowl of the sink

3024-install shower head

3022-Complete electrical at sink, bad gfci at peninsula, spark rings at party wall, address deck threshold height

3027-secure mc and firecaulk linesets at mechanical, threshold height at deck, loose receptacle near cooktop

3021-secure mc at mechanical

3023-bad gfci at living and kitchen, bad afci breaker at #24 Mechanical 23/25-complete electrical, install sprinkler escutcheon 3025-ok

4021 ok 4004-complete fire alarm 4005-Gfci 4006 ok 4021-ok 4027-GFCIs at cooktop 4008-ok 4025- j box covered in wall at benches, address sprinkler head by light in hallway 4023-gfci at island 4010- smoke seal, secure mc, switch plate 4027-Smoke seal, secure mc 4022-complete hvac unit 4024-GFCI at master vanity, missing hvac unit 4029-secure dishwasher discharge line, repair ceiling/complete electrical in den, GFCI at washing machine, install hvac unit 5024-Bath fan, hook up dishcharge line, instatll VTAC 5029-Install VTAC 5022-GFCI at countertop 5027-Seal penetrations at mechanical closet 5023-Junction box at bench storage to remain accessible 5025-Junction box at bench storage to remain accessible 5101-Missing escutcheon

5021-Bath fan

Comments: