

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20225233
Address: 3073 NW THOREAU LN, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Shawn Hoffman	Failed	Wednesday, November 30, 2022

Corrective Action Required:

1	Misc	- 302.11 Fire block horizontally at intervals of 10' and fire block fur out at top plate on exterior walls - Combustion air required - Support all soffits and ceiling fur down s wider than 4' to joists - Fire block ceiling height changes - Complete electrical outlet boxes (piano room)
---	------	--

Comments: