

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRSUBD20215636  
Address: 451 SW LONGVIEW BLVD, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

| Inspection:                                      | Inspector: | Outcome: | Date:                     |
|--|------------|----------|---------------------------|
| <b>Erosion Sediment Control (ESC) Inspection</b> | Eric Sharp | Partial  | Monday, December 12, 2022 |

Informational:

|   |      |   |
|---|------|---|
| 1 | Misc | Erosion control measure installed around perimeter of project site. 9/6/22 ES   |
|   |      | 9-20-22 RH. Erosion control is in place and in working order.   |
|   |      | Erosion control installed, intact and functioning. 9/26/22 ES   |
|   |      | Erosion control measures installed, intact, and functioning. 10/3/22 ES   |
|   |      | Erosion control measures installed, intact, and functioning. 10/10/22 ES  |
|   |      | Erosion control measures installed, intact and functioning. 10/18/22 ES   |
|   |      | Rain event 10/24. Erosion control measures unable to contain some runoff of open storm trenches allowing some silt to make its way through to basin on SE side of Kessler drive. Most other erosion control measures intact and functioning to contain erosion on site. 10/25/22 ES |
|   |      | Erosion control measures installed, intact, and functioning. 10/31/22 ES  |
|   |      | Erosion control measures installed, intact, and functioning. All vehicles were parked around perimeter of site and no erosion issues noted. 11/7/22 ES  |

11-14-22 RH. Erosion control is in place and working order. One corner of the silt fence was starting to fail but not yet. This was informed to the contractor.

Erosion control measures installed, intact, and functioning. The corner of concern has not failed, but also does not appear to have been addressed.  
11/21/22 ES

12-12-22 RH. Erosion control is up and in working order.

**Comments:**