



LEE'S SUMMIT MISSOURI



FIRE DEPARTMENT

NOTIFICATIONS/CONTACT INFORMATION SECTION

PAGE 1

☐ CHANGES

| | | | |
|----------------------------|---|------------------|----------------|
| BUSINESS NAME | JOHN KNOX VILLAGE MEADOWS PHASE II - INDEPENDENT LIVING APARTMENTS | | |
| ADDRESS | 1801 NW OBRIEN RD, LEES SUMMIT, MO 64081520 NW HOPE LN, LEES SUMMIT, MO 64081 | | |
| OWNER/OPERATOR NAME | HAREN CONTRACTING: | TELEPHONE | (913) 495-9558 |
| ADDRESS | 8035 NIEMAN RD LENEXA, KS 66214 Primary: (913) 495-9558 Cell: (913) 271-8171 | | |

EMERGENCY CONTACT INFORMATION

| NAME | TELEPHONE |
|----------|-----------|
| 1. _____ | _____ |
| 2. _____ | _____ |
| 3. _____ | _____ |
| 4. _____ | _____ |

LOSS REDUCTION TYPE

| | | | | | |
|------------------------------------|--|---------------------------------|--|---------------------------------------|--|
| <input type="checkbox"/> Occupancy | <input type="checkbox"/> Semi-Annual | <input type="checkbox"/> Annual | <input type="checkbox"/> Life Safety | <input type="checkbox"/> Sprinkler | <input type="checkbox"/> Hazardous Material Permit |
| <input type="checkbox"/> Complaint | <input type="checkbox"/> Explosive Storage | <input type="checkbox"/> UST | <input type="checkbox"/> Post-Incident | <input type="checkbox"/> Open Burning | <input type="checkbox"/> Other |
| CLASS: R-2 | Map#: | PFA#: | KNOX BOX: | KNOX LOCATION: | PERMIT # |

LOSS REDUCTION NARRATIVE

☐ NO VIOLATIONS NOTED

☐ ALL VIOLATIONS RESOLVED

Last Inspection

1st Inspection

2nd Inspection

3rd Inspection

4th Inspection

| | | | |
|---|------------------|----------------|----------------------------|
| INSPECTION | INSPECTOR | OUTCOME | DATE |
| Alarm Test | Craig Hill | Failed | Tuesday, December 13, 2022 |
| Corrective Action Required: | | | |
| 1 6 rooms did not have notification working. Horn strobe for water flow did not operate properly. Fire doors did not operate. | | | |

| | | | |
|---|------------|--|------------------------------|
| Sprinkler - Hydrostatic Test | Craig Hill | Passed | Monday, November 21, 2022 |
| Sprinkler - Flow Test | Craig Hill | Passed | Tuesday, December 13, 2022 |
| Alarm Test | Craig Hill | Failed | Wednesday, December 14, 2022 |
| Corrective Action Required: 1 Fire doors did not drop on alarm activation. Horn strobe for water flow did not operate properly. | | | |
| Alarm Test | Craig Hill | Passed | Thursday, December 15, 2022 |
| Occupancy Inspection - Fire | Craig Hill | Failed | Monday, December 19, 2022 |
| Corrective Action Required: 1 2030 master, closet, escutcheon 3028 laundry room sprinkler head missing. 3024 Laundry room sprinkler head missing EXIT signs | | | |
| DATE OF REPORT | INSPECTOR | PREVENTION FOLLOW-UP REQUIRED? | RESPONSIBLE SIGNATURE |
| December 19, 2022 | Craig Hill | <input type="checkbox"/> Yes <input type="checkbox"/> No | |