CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRRES20222281Address:2151 NW KILLARNEY LN, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Mitchell Schwarz	Failed	Wednesday, December 28, 2022
Corrective Action Required	-(5) 2x6 per plans at be -address exterior wall -nail cspf straps at rear -address penetrations -fireblock foyer closet space above -fire block loft wall spa -fire block wall space t -address stud notched -seal penetrations arour room entry -seal penetrations in ja -ensure all anchor bolt -anchor bolt to be with the diameter of the bo	stud notched for anch slider completely in office closet dead s wall space to garage b ace to ceiling space o ceiling space at bed for anchor bolt in unf und steal column into bist space used for ret s are tight hin the first 12" of sill p lt(see near basement for dwv in joist space	beam horizontal space and ceiling 3 closet for hvac inished right of service panel furr down at basement bed urn air in basement bedroom plate ends but not closer than 7x