## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

## **Inspection Summary**

Permit #: PRRES20215067 Address: 2032 SW HOLDBROOKS DR, LEES SUMMIT, MO 640822034 SW HOLDBROOKS DR, LEES SUMMIT, MO 640822036 SW HOLDBROOKS DR, LEES SUMMIT, MO 640822038 SW HOLDBROOKS DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
All Rough Inspection - Residential		Patrick Schonfeldt	Failed	Wednesday, December 28, 2022
Corrective	Action Required:			
1	Misc	UNIT 2038: -Fire rated wall to extend to roof deck, R302.2.3 Continuity. The fire-resistance-rated wall or assembly separating townhouses shall be continuous from the foundation to the underside of the roof sheathing, deck or slab. The fire-resistance rating shall extend the full length of the wall or assembly, including wall extensions through and separating attached enclosed accessory structures.(PROVIDE H STUDS AND C CHANNEL AT FIRE ROCK PER ENGINEERED DESIGN, SEE PLANS A7.0, NAIL PENETRATIONS IN ROCK, H STUDS MODIFIED LOOKS LIKE FACE SCREWED?)		
		UNIT 2036: OK		
		UNIT 2034: -fireblock at mechanical/pl around plumbing at fireblo	umbing fur out garage wall, ck material	seal annular space
			o roof deck, R302.2.3 Contin r assembly separating townl	•

continuous from the foundation to the underside of the roof sheathing, deck or slab. The fire-resistance rating shall extend the full length of the wall or assembly, including wall extensions through and separating attached enclosed accessory structures. (PROVIDE H STUDS AND C CHANNEL AT FIRE ROCK PER ENGINEERED DESIGN, SEE PLANS A7.0, ROCK NOT SEATED IN H STUDS, BOWING OUT, H STUDS MODIFIED LOOKS LIKE FACE SCREWED?)

**Comments:**