



December 29, 2022


Summit Homes
120 SE 30th St.
Lee's Summit, MO 64082

RE: Field Issue for Lot #95 Reserve at Stoney Creek – 1708 Hightown Dr. Lee's Summit, MO 64082 – Permit # PRRES20216531

Field issue of LP panel siding not extending over upper top plate

Recommended modifications:

- **Install 2x4 blocking underneath top plate in stud bays for areas where LP siding does not extend to the top plate.**
 - **Strap blocking w/ a continuous 4' CS16 strap to adjacent structural members in bedroom #1 where WSP is located.**
 - **Attach blocking to double top plate w/ 4" structural screws top and bottom per bay in bedroom #1.**
 - **See detail below for blocking in Great room and Dining Room.**
 - **Fasten siding to blocking w/ 10D nails in 6" nail pattern.**



Sincerely,

A handwritten signature in blue ink, appearing to read "B. Huxol".

Bradley Huxol, PE

