



LEE'S SUMMIT MISSOURI



FIRE DEPARTMENT

NOTIFICATIONS/CONTACT INFORMATION SECTION

PAGE 1

☐ CHANGES

BUSINESS NAME	SIGNATURE AT WEST PRYOR PHASE 2 - BUILDING 2		
ADDRESS	2150 NW LOWENSTEIN DR, LEES SUMMIT, MO 64081		
OWNER/OPERATOR NAME	BRINKMANN CONSTRUCTORS:	TELEPHONE	(636) 537-9700
ADDRESS	16650 CHESTERFIELD GROVE RD CHESTERFIELD, MO 63005 Primary: (636) 537-9700 Cell: <NO CELL PHONE>		

EMERGENCY CONTACT INFORMATION

NAME	TELEPHONE
1. _____	
2. _____	
3. _____	
4. _____	

LOSS REDUCTION TYPE

<input type="checkbox"/> Occupancy	<input type="checkbox"/> Semi-Annual	<input type="checkbox"/> Annual	<input type="checkbox"/> Life Safety	<input type="checkbox"/> Sprinkler	<input type="checkbox"/> Hazardous Material Permit
<input type="checkbox"/> Complaint	<input type="checkbox"/> Explosive Storage	<input type="checkbox"/> UST	<input type="checkbox"/> Post-Incident	<input type="checkbox"/> Open Burning	<input type="checkbox"/> Other
CLASS: R-2	Map#:	PFA#:	KNOX BOX:	KNOX LOCATION:	PERMIT #

LOSS REDUCTION NARRATIVE

☐ NO VIOLATIONS NOTED

☐ ALL VIOLATIONS RESOLVED

Last Inspection

1st Inspection

2nd Inspection

3rd Inspection

4th Inspection

INSPECTION	INSPECTOR	OUTCOME	DATE
Alarm Test	Craig Hill	Not Ready	Wednesday, January 11, 2023
Sprinkler - Hydrostatic Test	Craig Hill	Passed	Wednesday, January 11, 2023
Sprinkler - Flow Test	Craig Hill	Passed	Wednesday, January 11, 2023

Alarm Test

Craig Hill

Passed

Wednesday, January 18, 2023

Corrective Action Required:

1 Add strobe sunder bases to ADA rooms. Item to be checked on final.

Occupancy Inspection - Fire

Craig Hill

Failed

Monday, January 23, 2023

Corrective Action Required:

1 Covered head, storage room, third-floor 342
367 sprinkler head deflector on the deck
Stand pipe caps
Elevator key
Storage 1st floor south 159 rscutcheon on sprinkler missing

DATE OF REPORT	INSPECTOR	PREVENTION FOLLOW-UP REQUIRED?	RESPONSIBLE SIGNATURE
January 23, 2023	Craig Hill	<input type="checkbox"/> Yes <input type="checkbox"/> No	