

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20220899

Address: 1024 NW BLACK TWIG CIR, LEES SUMMIT, MO 640811026 NW BLACK TWIG CIR, LEES SUMMIT, MO 640811028 NW BLACK TWIG CIR, LEES SUMMIT, MO 640811030 NW BLACK TWIG CIR, LEES SUMMIT, MO 640811032 NW BLACK TWIG CIR, LEES SUMMIT, MO 640811034 NW BLACK TWIG CIR, LEES SUMMIT, MO 640811036 NW BLACK TWIG CIR, LEES SUMMIT, MO 640811038 NW BLACK TWIG CIR, LEES SUMMIT, MO 640811040 NW BLACK TWIG CIR, LEES SUMMIT, MO 640811042 NW BLACK TWIG CIR, LEES SUMMIT, MO 640811044 NW BLACK TWIG CIR, LEES SUMMIT, MO 640811046 NW BLACK TWIG CIR, LEES SUMMIT, MO 640811022 NW BLACK TWIG CIR, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Commercial</b>	Robb Popp	Failed	Friday, January 27, 2023

Corrective Action Required:

1 Misc

1022

-Nail exterior corners in garage, provide ufer ground, strap top plates at exterior living room, seal penetrations at ceiling line in master, missing studs at master bed exterior door

1024

-Missing ladder trusses, protect dryer ducts, seal dead space by entry, missing studs at master exterior door

1026

-Strap top plate at dining room and living room, seal top plates at master, missing studs at master exterior door

1028

-Seal top plate at garage, anchor bolt at plate break in garage, seal dead space at entry, seal penetrations at master, missing studs at master door,

protect dryer ducts,

1030

-Seal penetration at garage door, nail corners at garage, strap top plate at dining, missing sheer trusses master, missing studs at master, protect dryer duct,

NOT INSPECTED:

1032

1034

1036

1038

1040

1042

1044

1046

**Comments:**