

Permit Fee Adjustment Form

Customer: Emery Sapp and Sons -- Matt Forbes

Permit #: PRSITE20221062

Address: 904 NW Pryor Rd.

Lees Summit MO 64081

Phone:

Email:

Notes: Meter was broke due to freezing temperatures and not having a properly installed meter well, ring and lid.

Description: Please add description details in their entirety on the invoice

Replacement of a broken meter due to contractor negligence.					
Line	GL Account	Account	Qty	Unit	Amount
1		Labor			\$315.00
2		Materials (Other Revenue-Taxable)			\$641.95
3		Equipment			\$90.88
4		ROW			
5					
6					
7					

Subtotal \$1,047.83

Sales Tax \$0.00

Total \$1,047.83

SR #	
WO #	

Prepared By: Brent Dye

Approved By: Brent Boice

Dept: Water Utilities

Date: 2/10/2023

Date: 2/10/2023