CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20215208

Address: 209 NW AMBERSHAM DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Erosion Control Mitchell Schwarz Failed Wednesday, February

22, 2023

Corrective Action Required:

1 DCM1 ESC EROSION CONTROL REQUIRED. NO FURTHER INSPECTIONS WILL BE

REQUIRED NO PERFORMED UNTIL EROSION CONTROL IS INSTALLED AND IN COMPLIANCE.

FURTHER INSP

Corrective Action Required:

2 DCM2 ESC DEFICIENT EROSION CONTROL INSTALLATION. NO FURTHER INSPECTIONS

DEFICIENT UNTIL ADEQUATE EROSION CONTROL PROVIDED.

INSTALLATION

Corrective Action Required:

3 DCM3 ESC EROSION CONTROL REQUIRED. EROSION CONTROL SHALL BE IN COMPLIANCE

REQUIRED 2 DAY WITHIN TWO BUSINESS DAYS.

Comments: